

Carbon Technology

Industrial Motors and Mass Transit Technology

Carbon Brushes – Order Guide



Carbon Brushes - Order Guide

With this information sheet we like to give our customers a tool to facilitate the order procedures of carbon brushes. It will show on the following pages the information required, to enable us to suggest the most appropriate carbon design and carbon grade for your application. It further assures a speedy and smooth handling of any order.

The easiest and fastest way for us to determine the correct design, is to receive a new or used sample of your present brush. This will eliminate the need to furnish other pertinent information regarding the proper design.

Should it however not be possible to provide an actual sample, we kindly request as much information as possible. This order guide will be a tool to help establish the required data.

We kindly ask you to fill out the Carbon Brush Order Guide as complete as possible and record in particular the presently used carbon grade.

Our manufacturing program covers carbon brushes for any possible electro motor application. Many styles are available ex stock on short notice.

For carbon brushes with attachments we reserve the right to provide the most suitable method of mounting between carbon brush and shunt, and between shunt and shunt-terminal.



Block brushes, one shunt



Block brushes, two or more shunts



Twin brushes





Pair brushes



Block brush - triple mounted



Triple brush





Brush Dimensions

The dimensions of carbon brushes are measured in the following sequence

txaxr

- Terminal

- Design

- t = tangential (in direction of circumference - i. e. thickness)
- **a** = axial (in direction of axle i. e. width)
- r = radial (in direction of diameter - i. e. length, incl. head plate)

Please be request to indicate the dimensions in this sequence.

If other than rectangular designs of carbon brushes are required, please indicate additional information, e.g. bevel of contact surface, contact surface slots, etc. For beveled brushes please specify the angle of running- and head-bevel.





For carbon brushes with fittings additional information is required. Please see the following **example**:



Explanation:

S = Shunt length, measured from top of brush to center of terminal, respectively center of terminal bolt M = Size of terminal bolt, e.g. "M6"

Example

Brush Design: Figure No. 26 (see page 3) **Brush Dimension:** txaxr e.g. 10 x 25 x 32mm Shunt Length: S = e. g. 75mm Design of Terminal: e.g. Figure No. B1 Width of Slot: e.g.6mm (M6)

Carbon Brushes Order guide

Customer address

schunk

Name Street	RFQ / order no Quantity
Postal Code City	Email
Brush design	Brush grade
Brush design Figure no	(* to be completed, if grade unknown) Machine manufacturer*
Brush dimensions txaxrmm	Commutator Slipring
Upper angle 7,5° 🔲 15° 🔲 30° 🔲	Machine type*
Lower angle 7,5° \Box 15° \Box 30° \Box	Generator Type of current
if running surface radiused: Commutator ø mm	AC
Slipring ø mm	Normal voltageV Normal currentA
Length mm Insulation	Current brush grade
Tinned L Plain	Notes
Terminal Figure no.	
Gap mm Hole ø mm	

The Schunk Group is an internationally operating technology company. It offers a broad spectrum of products and services in the fields of carbon technology and ceramics, environment simulation and air conditioning technology, sintered metal and ultrasonic welding. The Schunk Group has bundled its expertise in the development, manufacture and application of carbon and ceramic solutions in the Schunk Carbon Technology Division.

Schunk Kohlenstofftechnik GmbH

Rodheimer Strasse 59 35452 Heuchelheim ¬ Germany Phone +49 (0) 641 608 0 Fax +49 (0) 641 608 1748 E-Mail infobox@schunk-group.com www.schunk-group.com

